INTERNATIONAL TOOL MANUFACTURING 150 Express St. Plainview, NY 11803

(516) 738-0388 • (800) 247-5696 Fax (516) 279-1106





Notice: Core Bit drilling without the use of a pilot drill bit causes excessive pressure on system. This can result in breakage to the extension at the tapered end, especially be slots. Such jagged breaks are not considered defective and may not be covered under w